

Oil Field Environmental Incident Summary

Incident: 20201223133430 **Notice:** 12/23/2020 13:34 **Occurred:** 12/23/2020 10:00

Responsible Party: WHITING OIL AND GAS CORPORATION

Well Operator: WHITING OIL AND GAS CORPORATION

Well Name: P WOOD 154-98-4-26-35-13H3

Field Name: TRUAX

Well File #: 25178

Facility ID #:

County: WILLIAMS

Twp Rng Sec Qtr: 154 98 26 NW NW

Location Description: Pad lat/long is 48.137512 -103.256403

Submitted By: Brian Wurm

Received By:

Contact Info: Brian Wurm
1700 Lincoln, Ste 4700
DENVER CO 80203

Affected Medium: Topsoil

General Land Use: Pasture

Near. Occupied Bldg: 1 Mile

Nearest Water Well: 1 Mile

Type of Incident: Treater Popoff

Release Contained: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	2	Gallons	2	Gallons		

Brine

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

Minimal risk anticipated. The release is stopped and cleanup is in progress.

Areal Extent:

To the south east approximately 30' by 30'

Potential Env. Impacts:

Minimal environmental impacts anticipated. The release is stopped and cleanup is in progress.

Action Taken/Planned:

The wells were shut in to stop further incident. A crew is onsite to clean up release on pad and offsite impacts will be addressed to landowner recommendations.

Wastes Disposal Location:

Any impacted material that needs to be removed will be taken to an approved nearby landfill.

Other Agencies Involved:

Updates

Date: 12/23/2020 **Status:** Reviewed - Follow-up Required

No Further Action: ☐

Author: Lund, Dylan

Notes:

According to the incident report, a small release was not contained. Follow-up is necessary.

Updated Volumes and Contaminant None at the time of this update

Date: 1/6/2021 **Status:** Inspection - Vegetation Check

No Further Action: ☐

Author: Suess, Bill

Notes:

Inspected the site on 1/5/2021. At the time of the inspection a 30 foot by 30 foot area off the SE corner of the well pad had already been mowed and remediated. The site should be inspected in the spring of 2021 to assure proper revegetation.

Updated Volumes and Contaminant None at the time of this update

Date: 6/7/2021 **Status:** Inspection - More Follow-up Required

No Further Action: ☐

Author: Lund, Dylan

Notes:

Arrived on location at 1710 on 6-7-2021.

No vegetation in affected area. Appears the impacted soils have not been properly remediated. Company should be contacted regarding future plans. Photos were taken and can be found in incident folder.

Updated Volumes and Contaminant None at the time of this update

Date: 11/23/2021 **Status:** Inspection - Vegetation Check

No Further Action: ☐

Author: Lund, Dylan

Notes:

Arrived on location at 2:25pm on 11-23-2021.

Impacted area is still bare of vegetation. More work might need to be done if nothing grows next spring/summer. Another vegetation check required. Photos were taken and can be found in the incident folder.

Updated Volumes and Contaminant None at the time of this update